UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,133,307 B2

DATED

APPLICATION NO.: 10/674550

INVENTOR(S)

: November 7, 2006

: R. Jacob Baker

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification, the following errors are corrected:

Column 3, line 63, "dock" should read --clock--;

Column 5, line 13, "dock" should read --clock--;

Column 5, line 57, "dock" should read --clock--;

Column 5, line 62, "dock cycle of dock" should read --clock cycle of clock--;

Column 6, line 41, "dock" should read --clock--;

Column 6, line 42, "dock" should read --clock--; and

Column 6, line 56, "docked" should read --clocked--.

In Claim 9, the following errors are corrected:

Column 8, line 19, "reservoir" should read --storage device--;

Column 8, line 33, "reservoir" should read --storage device--;

Column 8, line 34, "reservoir" should read --storage device--; and

Column 8, line 35, "reservoir" should read --charge storage device--.

Signed and Sealed this

Page 1 of 1

Sixteenth Day of January, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office